



SAFETY BULLETIN:

SLIPS, TRIPS & FALLS



According to the National Ready Mixed Concrete Association (NRMCA), slips, trips and falls account for the majority of all workplace accidents. During the winter months, this reality is highlighted by more muddy, wet and icy walking and working surfaces. To reduce and ultimately eliminate slips, trips and falls, and the injuries and costs associated with them, ready mixed concrete producers should take just a few minutes to assess their operations and any liabilities

Ready mixed concrete production facilities should have all employees review procedures at plants for walking, working surfaces and fall protection on a regular basis. Reviews should include regular inspections followed by any necessary fixes, changes, or updates to surfaces

ACTIONS

- Think first.
- Use 3 points-of-contact when ascending or descending stairs or ladders.
- Keep focused on footing and handrails.
- Limit slippery or icy surfaces.
- Keep surfaces dry.
- Adhere to proper housekeeping.
- Eliminate obstacles.
- Spread sand and/or salt.
- Use boot/shoe crampons or cleats.
- Lay out anti-slip mats or treads.
- Maintain proper lighting.



RESOURCES

For more information on slips trips and falls please follow the links below:

- [NRMCA: Safety Series](#)
- [OSHA: Winter Weather Preparedness](#)
- [OSHA: Fall Protection & Walking](#)
- [OSHA: Cold Weather Working](#)
- [OSHA: Working Surfaces](#)